

STANDARD WIRING CODE

Lead	Cable Color	6 Pin Connector
Excitation +	White	C
Signal +	Red	A
Excitation -	Green	D
Signal -	Black	B
Calibration	Blue	E
Calibration	Orange	F

